SYMBOL DEFINITION		MISSING SYMBOL(S)
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL CODE MAY REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.	TOTAL NO OF INSPECTIONS REQUIRED: 11 LOT NO. SIZE: 11	NO MISSING SYMBOL NUMBER

REV LTR	REV DATE	REV ZONE	REVISION DESCRIPTION	ECN	DR
JD:A7E	8	17	ALL PARTS - ZEORED REV COLORS, REDRAWN WEL (W) TO PL CORRECTED PN (D51196) TERMINALS WAS (D51195) ADDED NOTE 10 ADDED NOTE 11 ADDED NOTE 12 ADDED THE REVISED "WATCHA PART NUMBER" CHART	X5E7B1	DM
JD:A7E	9	19	ALL PARTS - UPDATED "WATCHA PART NUMBER" CHART ADDED NOTE 13 ADDED NOTE 14	X3A7	JDM
13E:D	9	25	CIRCUIT NO. (D5197), (D5196) (D5195) (D5194), (D5193), (D5192), (D5191) (D5190) (D5189) (D5188) (D5187) (D5186) (D5185) (D5184) (D5183) (D5182) (D5181) (D5180) (D5179) (D5178) (D5177) (D5176) (D5175) (D5174) (D5173) (D5172) (D5171) (D5170) (D5169) ADDED NOTE 15 (D5168) ADDED NOTE 16 (D5167) ADDED NOTE 17 (D5166) ADDED NOTE 18 (D5165) ADDED NOTE 19 (D5164) ADDED NOTE 20 (D5163) ADDED NOTE 21 (D5162) ADDED NOTE 22 (D5161) ADDED NOTE 23 (D5160) ADDED NOTE 24