

SYMBOL DEFINITION				MISSING SYMBOLS												
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL □ DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.		TOTAL NO OF INSPECTIONS REQUIRED	14	NO MISSING SYMBOL NUMBER	DWG STATUS				ZONE	REVISION HISTORY		AUTH	DR	APVD	APVD	
					DATE	STG	REV	N/P								CHG
					25FEC02	R	01	-	-		ALL PARTS - CREATED PD, ADDED OPTIONAL LOGO AND MATERIAL RECYCLING CODE NOTES, REVISED GRAPHICS & REVISED MATERIAL SPEC		221541	JGR	EDV	JH
		LAST NO. USED	7		28OC02	R	02	-	-		ALL PARTS - ADDED KNOCKOUT PADS (4 PLCS)		232806	RM	HH	ET