




SYMBOL DEFINITION			MISSING SYMBOLS									
A DIMENSION WITHOUT AN INSPECTION REPORT SYMBOL DOES NOT REQUIRE INSPECTION. IT MAY BE CONTROLLED ON THE INDIVIDUAL COMPONENT DRAWING.			DMS STATUS		ZONE		REVISION HISTORY				AUTH	OK APPR
			DATE	STD REV IN P	DMS							
			100002	R F2	-		WAS ON TAXI (LX2943702; MAT'L SPEC WAS R010000P) & ADDED NOTES (2 FLTS)				229931	BURDETTE
TOTAL NO OF INSPECTIONS REQUIRED			15	NO MISSING SYMBOL NUMBER								
LAST NO. USED			13									



- NOTES
1. UNLESS OTHERWISE SPECIFIED AND/OR INDICATED:
DIMENSIONS ARE TO FACE OF VIEW SHOWN AND
AUTOMATICALLY ROUNDED BY COMPUTER FOR INSPECTION
SEE MATH MODEL FOR PRECISE DIMENSIONS. FOR ALL
OTHER DIMENSIONS NOT SHOWN BUT REQUIRED FOR TOOL
BUILD, SEE MATH MODEL FOR PRECISE TOOL PATH DATA.
 2. MATERIAL RECYCLING CODE %BCT PER SAE J1344. ((1.8X10.1)) RAISED
CHARACTERS TO BE LOCATED ON ANY EXTERIOR SURFACE.
OPTIONAL CONSTRUCTION TO BE NO MATERIAL RECYCLING CODE.
 3. THIS PART IS NOT CONTROLLED FOR AUTOMATIC FEEDING.
 4. ((1.8X10.1)) RAISED DELPHI CORPORATE BRAND TO BE LOCATED ON ANY
EXTERIOR SURFACE. PREFERABLY VISIBLE AT FINAL ASSEMBLY.
OPTIONAL CONSTRUCTION TO BE NO MATERIAL RECYCLING CODE.

OPTIONAL CONSTRUCTION

[illegible]